

PROVA-11 AC/DC mA True RMS Clamp Meter



FEATURES

- Super High Resolution DC 1mA, AC 0.1mA
- One Touch Zero for DCA
- True RMS



SPECIFICATION

Range	Output	Accuracy	
DCA 0-4000mA	1mA	+/- 1.5%rdg +/- 5dgts	
DCA 0-30A	10mA	+/- 1.5%rdg +/- 3dgts	
ACA 0-400mA	0.1mA	+/- 1.5%rdg +/- 5dgts	True RMS
ACA 0-4000mA	1mA	+/- 1.5%rdg +/- 8dgts	True RMS
ACA 0-30A	10mA	+/- 2.0%rdg +/- 5dgts	True RMS
DCV 0-400V	0.1V	+/- 1.0%rdg +/- 3dgts	
ACV 0-400V	0.1V	+/- 2.0%rdg +/- 5dgts	True RMS

Power Source:

2 X 1.5V AA UM3 Batteries

Current Consumption: 10mA

Operating Condition:

-10 °C to 50 °C at 85% max. RH